FIELD INSPECTION REPORT

Date of I	nspection: 4	101.2021	District: Sifamarhi	
Division: Belsand			Length (km): 0 1 0	
Name of	the Road: Nan	-dan Ram Ke g	than Separtapur se G	isara pa
	Programme:	MAINTENANCE		
			Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance				
Work is a case of: New Connectivity/U			p gradation/ Maintenance	
SI. No.	Parameters to be checked		Remarks	
1.	Pavement			
a)	Road Junction condition			✓S/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			√\$/U
d)	Road Camber ·			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
n	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c) .	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Ycs/No
4.	Compliance History			
	Status of ATD's & any others			No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signib Ahmad Junior Engineer Seq inb (Signature)