

FIELD INSPECTION REPORT

Date of Inspection :	04.01.2021	District:	Sidamahi
Division :	Belgaon	Length (km):	0.200 km
Name of the Road:	Khet Lal Ram house to Kizipur Bazar and Chak Jangpur Bazar		
Scheme/Programme:	MAINTENANCE (CH/MSRY)	Road Id No.:	
Package No.:		Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S) _____
 Satisfactory but requires Improvement (SRI) _____
 Unsatisfactory (U) _____

N. K. Jha
 (Signature)

NAME: NIKAS KUMAR