

FIELD INSPECTION REPORT

MMSY
NDB (BRKS)

Date of Inspection : 12-12-2020		District: Samastipur
Division : Samastipur		Length (km): 1.065 km
Name of the Road: L042 Bejadih to Shitalpatti		
Scheme/Programme: MAINTENANCE		
Package No.:		
Status of the Project:	Road Id No.: 32010101909	
Work is a case of:	Ongoing/Completed/Under Maintenance	
	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U U
d)	Road Camber	S/U U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating : Remarks - BT top surface damage & E/W in shoulder neg.

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

NAME: SANTOSH KR. THAKUR
JE, RWD Samastipur-2

Santosh
14-12-2020

(Signature)
AE

SR
14/12/20
AE