FIELD INSPECTION REPORT

Date of Inspection: 13 1.21 Division: Rexaul		District: East damperan			
Name of the Park			Length (km): 0.989		
Schem	e/Programmas Ju	afor to che	he KatLavia	to a distribution of the commence.	
Packag	ge No.:	MAINTENANCE	MASSY (BEN)	· · · · · · · · · · · · · · · · · · ·	
Name of the Pant June for to chiefe ka Scheme/Programme: MAINTENANCE MMS. Package No.: Road to Status of the Project: Ongoing/Completed/Under M			Index Maintenance	INO.: 31708501232	
Would		gradation/ Maintenance			
Sl. No.		Parameters to be checked		Remarks	
 1. Pavement a) Road Junction condition b) Condition of Surfacing 					
		ondition		S/U	
		acing	118	S/U	
c)	Riding Quality		on with cracks exposed	S/U	
d)	Road Camber		7.7	S/U	
e) Whether free from del aggregates in case of CC I		0111 (1010010) 3(1011	as visible cracks, exposed	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No		
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U		
b)) Condition of Abutment & Wing walls,		Slab in RCC culverts	S/SRI/U	
c) Condition of railings/slab/approach for		Bridges	S/SRI/U		
3.	Road Furniture				
1) s	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
. 0	Compliance History				
) S	tatus of ATR's & a	ny others			

Overall Rating

Satisfactory (S)	6/
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: MALLES Kromer Sivol
DESIGNATION: Junor Epikeer, Maur Jano