

# FIELD INSPECTION REPORT

Date of Inspection : 04.01.2021  
 Division : Belband  
 District : Silamarkh  
 Name of the Road : Amiri Sah be ghar se Nainawa Bandh Sirbhira Jola  
 Length (km): 0.150 km  
 Scheme/Programme: MAINTENANCE (CST/SNY)  
 Package No.:  
 Road Id No.:  
 Status of the Project: Ongoing/Completed/Under Maintenance  
 Work is a case of: New Connectivity/Up gradation/ Maintenance

| Sl. No. | Parameters to be checked                                                                                              | Remarks |
|---------|-----------------------------------------------------------------------------------------------------------------------|---------|
| 1.      | <b>Pavement</b>                                                                                                       |         |
| a)      | Road Junction condition                                                                                               |         |
| b)      | Condition of Surfacing                                                                                                | ✓S/U    |
| c)      | Riding Quality                                                                                                        | ✓S/U    |
| d)      | Road Camber                                                                                                           | ✓S/U    |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                          | ✓Yes/No |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                      | ✓Yes/No |
| g)      | Compaction of flank/slope & raincuts if any                                                                           | ✓Yes/No |
| 2.      | <b>Cross Drainage</b>                                                                                                 |         |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                  | S/SRI/U |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                              | S/SRI/U |
| c)      | Condition of railings/slab/approach for Bridges                                                                       | S/SRI/U |
| 3.      | <b>Road Furniture</b>                                                                                                 |         |
| a)      | Whether sign boards/informatory, cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓Yes/No |
| 4.      | <b>Compliance History</b>                                                                                             |         |
| a)      | Status of ATR's & any others                                                                                          |         |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

*(Signature)*  
 (Signature)

NAME: NIKAS KUMAR