FIELD INSPECTION REPORT

Date of I	spection: 2	2.12,2020.	District: Patna	
Division: Patna			Length (km): 125K M	
Name of		aid Puz Char	idasi Path to Prahl	ladehak
Scheme/I	Programme:	MAINTENANCE /	MMGSY (SC)	
Package		/	Road Id No.:	
Status of	the Project:	Ongoing/Completed	/Under Maintenance	
Work is	a case of:	New Connectivity/U	p gradation/ Maintenance	I
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/Ŭ
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/Ù
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U ∧
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U A
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance Hi	story		
a)	Status of ATR's	& any others		No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature)

NAME: Jaifrakash Singh.
DESIGNATION: JE