FIELD INSPECTION REPORT

Date of Inspection :	22/12/2020.	District: Patha
Division: Patra	. 0	Length (km): 0.45 K.M.
Name of the Road:	said fus chan	dasi) ath to Usta harijantola
Scheme/Programme:	MAINTENANCE/	MM GSX(SC)
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed	/Under Maintenance
Work is a case of:		p gradation/ Maintenance

Sl. No. Parameters to be checked		Remarks	
1.	Pavement		
a)	a) Road Junction condition		
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage	N)	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U /	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ^	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History	AT A COMME	
a)	Status of ATR's & any others	No.	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: Jai Prakach Singh.
DESIGNATION: J.E.