

FIELD INSPECTION REPORT

Date of Inspection :	05-12-2020	District:	Udalganj
Division :	Udalganj	Length (km):	2 km
Name of the Road:	MR - Howe Roadway through Jhilmong Pul		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing Completed Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U 'S'
b)	Condition of Surfacing	✓ S/U 'S'
c)	Riding Quality	✓ S/U 'S'
d)	Road Camber	✓ S/U 'S'
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓ No visible cracks
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓ provided
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U 'S'
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U 'S'
c)	Condition of railings/slab approach for Bridges	S/SRI/U ✓
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No ATR

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME:

DESIGNATION:

(Signature)