

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - *Gyan Rajbhakar*

2. Name of Block/Road - *Godampatti to Yagya toli (Gaighat)*

A. For Road

1. Damage Location/Chainage : *0.100km, 0.250km, 0.750km, 0.900km, 1.20km*
(Total = 1.40km)

2. Damage Length : *0.112 km*

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works : *brick bats.*

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length : *0.112 km*

X B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Signature of JE/AE/EE

[Signature]
28-12-20
Signature

(Name of Inspector)

EE
RWD. WORKS DIVISION
MYZSFFXPUS EAST-1

GENERAL ABSTRACT

Name of Road Godanpatti to Nayatoli

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km) 1.400 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
1	Jhama metal	2.439
2	Sand Filling	0.050
3	Sand Bag	0.000
4	Bamboo Piles	0.000
GRAND SUB TOTAL		2.497 2.439
TOTAL COST OF PROJECT IN LACS =		2.497 2.439

Say. 2.44 Lac.

(Signature)
 5/12/20
 JE
 RWD

(Signature)
 7/12/20
 AE
 RWD

(Signature)
 EE
 RWD

Technically Approved for Rs. 2.44 Lac.
 (Rupees two Lac, forty four thousand only).

(Signature)
 SE
 PWD work circle
 muzaffarpur