

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gayan vibhakar

2 Name of Block/Road :- mangheuli katra Road Raykobyasud keghar to munni kadyan
(Bochaha)

(A) For Road: ✓

1. Damage Location/Chainage :- 0.05km, 0.150km, 0.30km, 0.80km, 1.50km, 2.20km
2. Damage Length :- 1265.9 m (1.2659km) 2.90 km
3. Nature of Damage :- (Length = 3.174 km)
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick beds.
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 1.265 km (1.2659 km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE

RWD work Division,


myzathurpur Ecvt-1


GENERAL ABSTRACT


Name of Road Construction of Road From Majhauili Katra Road Ragho Prasad Ke Ghar to Munni Kalyana
District Muzaffarpur
Block Bochaha
Division Muzaffarpur East-2
Length of Road (in Km) 3.174 Km

| Sl. No. | DESCRIPTION | AMOUNT (LAKHS) |
|---------------------------------|-----------------|----------------|
| 1 | Jhama metal | 21.498 |
| 2 | Sand Filling | 0.000 |
| 3 | Sand bag | 0.000 |
| 4 | Bamboo Piles | 0.000 |
| | GRAND SUB TOTAL | 21.498 |
| TOTAL COST OF PROJECT IN LACS = | | 21.498 |


Says 21.50 lac


JE
RWD


AE
RWD


RWD

Technically Approved for Rs 21.50 lac
(Rupees twenty one lac fifty thousand only)


SE
RWD work circle
muzaffarpur