FIELD INSPECTION REPORT

Date of Inspection: 6-1-21			District: Melenda		
Division: Britansanif			Length (km): 2.10		
Same of	the Rond: But	har Nising, near 1	police stepion to sultamp	ws.	
	Programme:	MAINTENANCE	mm asy (se)		
Package	No.:		Road Id No.:		
Status of the Project: Ongoing/Completed/Under					
Work is	a case of:		Jp gradation/ Maintenance		
Sl. No.		Parameters to	he checked	Remarks	
1.	Pavement				
ລ)	Road Junction condition S.			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			s∕∪	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
Ŋ				Yes/No	
٦)	Compaction of flank/slope & raincuts if any			YesNo	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance History			-	
۵)	Status of ATR's & any others			Nil	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: Ram Akbal pd. Gingh yadar

DESIGNATION: Athispent Engineer