## FIELD INSPECTION REPORT

Divisio	f Inspection:	13/01/201	Length (km): A.O	26
	on: Den Cope of the Road: Finl	work Taniba	District: Later Length (km): 0,2	not mashha
		MAINTENANCE	1	Vordan
Scheme Packag		MAINTENANCE	Road Id No.:	
		Ongoing/Complete	d/Under Maintenance	, — · · ·
To the yar			Up gradation/ Maintenance	
Sli No.	a b asetron v isr	Parameters to	be checked	Remarks
1	Pavement	alia de la Sala		
a)	Road Junction condition			€8/U
b)	Condition of Surfacing			√8/U
c)	Riding Quality			√S/U
d)	Road Camber			₩/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			posed Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			vYes/No
20.1	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			inting 8/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			₽8/SRI/U
c)	Condition of railings/slab/approach for Bridges			√S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			200m Yes/No
4.	Complaince Histo	ney		
	19865	The state of the s	THE RESERVE TO SERVE THE PROPERTY OF THE PARTY OF THE PAR	ATTENNESS OF THE PROPERTY OF THE PARTY OF TH

**Overall Rating** 

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	1
Unsatisfactory (U)	

Status of ATR's & any others

Nigral NAME: - Nigmanand Mahto DESIGNATION: - J. E.