

# FIELD INSPECTION REPORT

| Date of Inspection : - 09/12/2020                    |                                                                                                                      | District: - Banka                          |
|------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|--------------------------------------------|
| Division : - Banka - I                               |                                                                                                                      | Length (km): 3.60                          |
| Name of the Road: Banka Belhar road to Sonagar Ranga |                                                                                                                      |                                            |
| Scheme/Programme:                                    |                                                                                                                      | MAINTENANCE                                |
| Package No.:                                         |                                                                                                                      | Road Id No.:                               |
| Status of the Project:                               |                                                                                                                      | Ongoing/Completed/Under Maintenance        |
| Work is a case of:                                   |                                                                                                                      | New Connectivity/Up gradation/ Maintenance |
| Sl. No.                                              | Parameters to be checked                                                                                             | Remarks                                    |
| 1.                                                   | <b>Pavement</b>                                                                                                      |                                            |
| a)                                                   | Road Junction condition                                                                                              | ✓S/U                                       |
| b)                                                   | Condition of Surfacing                                                                                               | ✓S/U                                       |
| c)                                                   | Riding Quality                                                                                                       | ✓S/U                                       |
| d)                                                   | Road Camber                                                                                                          | ✓S/U                                       |
| e)                                                   | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No ✓                                   |
| f)                                                   | Contraction Joints provided or not (CC Pavement)                                                                     | ✓Yes/No                                    |
| g)                                                   | Compaction of flank/slope & raincuts if any                                                                          | Yes/No ✓                                   |
| 2.                                                   | <b>Cross Drainage</b>                                                                                                |                                            |
| a)                                                   | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U                                    |
| b)                                                   | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U                                    |
| c)                                                   | Condition of railings/slab/approach for Bridges                                                                      | ✓S/SRI/U                                   |
| 3.                                                   | <b>Road Furniture</b>                                                                                                |                                            |
| a)                                                   | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓                                   |
| 4.                                                   | <b>Compliance History</b>                                                                                            |                                            |
| a)                                                   | Status of ATR's & any others                                                                                         |                                            |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            |     |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U)                          |     |

*[Signature]*  
09/12/2020  
(Signature)

NAME: - DINESH PD GUPTA

DESIGNATION: J.E.