

# FIELD INSPECTION REPORT

Date of Inspection :	17.12.20	District:	West Champaran
Division :	Beffiah	Length (km):	
Name of the Road:	L130-Mahavirpur to Masjid tola.		
Scheme/Programme:	MAINTENANCE PMGSY		
Package No.:		Road Id No.:	31808802307
Status of the Project:	Ongoing/Completed/Under Maintenance Under maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
<b>Sl. No.</b>	<b>Parameters to be checked</b>	<b>Remarks</b>	
<b>1.</b>	<b>Drainage</b>		
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing	S/U	S
c)	Riding Quality	S/U	S
d)	Road Camber	S/U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	S
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	S
g)	Compaction of flank/slope & raincuts if any	Yes/No	S
<b>2.</b>	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
<b>3.</b>	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	S
<b>4.</b>	<b>Compliance History</b>		
a)	Status of ATR's & any others	N/D	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Signature  
17/12/20  
(Signature)

NAME:

DESIGNATION:

Scanned by CamScanner

Scanned by CamScanner