

Date of Inspection: 15/11/21	District: NALANDA
Division: HUDA	Length from: 2.4 km
Name of the Road: Deogarh Bihar road to Chauri school via Bhatu Bigha	
Scheme/Programme: MAINTENANCE	
Package No.: NHG 14 NDA DRC's Road Id No.	
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Construction/Up gradation/Improvement	

Sl. No.	Parameters to be checked	
1.	Pavement	
a)	Road Junction condition	3
b)	Condition of Surfacing	3
c)	Riding Quality	3
d)	Road Camber	3
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	YES/NO
f)	Contraction Joints provided or not (CC Pavement)	YES/NO
g)	Compaction of flank slope & rainents if any	YES/NO
2.	Cross Drainage	
a)	Condition of head walls in flume pipe culverts including its painting	S/PS/NO
b)	Condition of Abutment & Wing walls. Slope in CC culvert	S/CR/U
c)	Condition of railings/slab/approach for bridges	N/A S/BR/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/kit & iron stones Pavement road markings are provided and maintained	YES/NO
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

[Signature]
15/11/21

ANJANE KUMAR
NAME: