

Date of Inspection:	15/11/21	District:	HAHAIDA
Division:	MUSA	Length (km):	2.45 km
Name of the Road:	Kangar Bazar road to Choral school via Bhatla Bigha		
Scheme/Programme:	MAINTENANCE		
Package No.:	MHC	NDP BRICs	Road Id No.
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/Improvement		
Sl. No.	Parameters to be checked		
1.	Pavement		
a)	Road function condition		3
b)	Condition of Surfacing		5
c)	Riding Quality		3
d)	Road Camber		5
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		YES/NO
f)	Contraction Joints provided or not (CC Pavement)		YES/NO
g)	Compaction of flank slope & raincuts if any		YES/NO
2.	Cross Drainage		
a)	Condition of head walls in culverts including its painting		S/S/CR/U
b)	Condition of Abutment & Wing walls, b/c in CC culverts		S/CR/U
c)	Condition of railings/slab/approach for Bridges	N/A	S/S/CR/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Sign & Con stones/Pavement road markings are provided and maintained		YES/NO
4.	Compliance History		
a)	Status of ATR's & any others	N/A	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NAME: JANE KUMAR

Signature
15/11/21