FIELD INSPECTION REPORT

		16. H. 21 District: West	Clampara	41	
Date of inspection:					
Direction . Bernie.					
Package No.: Road Id No.: 3/80 880/252					
Status of the Project: Ongoing/Completed/Under Maintenance engaing					
Work is a case of: New Connectivity/Up gradation/ Maintenance					
85-000	1	Parameters to be checked		nerio	
The state of	Pimement			44	
	Road Junction condition			7	
8)				īv V	
b)	Condition of Surfacing			บ	
c)	Riding Quality		S/	 1\	
q)	Road Camber	•			
e)	Whether free aggregates in o	from defects such as visible cracks, example of CC Pavement.	rposed Yes	No	
f)	Contraction Jo	ints provided or not (CC Pavement)	Yes	No NA	
g)	Compaction of	flank/slope & raincuts if any	Yes	No \	
	Cross Deninage				
a)	Condition of h	ead walls in Hume pipe culverts including its pa	inting S/SR	I/U	
b)	Condition of A	butment & Wing walls, Slab in RCC culverts	S/SR	עע	
c)	Condition of ra	ilings/stab/approach for Bridges	· S/SR	I/U	
3.	Road Furnitu	re			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4	Compliance H	istory			
8)	Status of ATR'	s & any others			
Overall:	Rating :	Satisfactory (S)		NA	
		Satisfactory but requires Improvement (S	RI)		
	•	Unsatisfactory (U)			
ote:-	work in	progress	findere.	16.01.21	
			(Signature)		
name:	IAME: J.E.				
DESIGNATION:					
es.					
•	•	•			

Scanned by CamScanner