Date of	Inspection: \	5.1.2121	District: w. champing		
Division: R-W-D. Politich			Length (km): 2-N31		
Name o	f the Road:	022 8 WY 9 de	into Barrola Tula		
	Programme:	MAINTENANCE			
Package No.:			Road Id No.: 3180 550 021)		
			Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
arch Whatle	s a case oi:	TOTAL CONTRACTOR OF THE PROPERTY OF		rishdebannasi/waa	
SI. No.	The state of the s	Parameters (o bo checked	Remarks	
i,	Pavement				
a)	Road Junction condition				
ъ)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber		p ^e e ^s	S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2,	Cross Drainag	C i			
a)	Condition of head walls in Hume pipe culverts including its painting				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Eurnitur	er i	Harry San Control of the Control of		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance H	sfory 5		i les messes	
a)	Status of ATR's	& any others		44	
		The state of the s			

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Rolmono Pd & Reghvardon Pel ST8h
DESIGNATION: J-18 & A-18