

FIELD INSPECTION REPORT

Date of Inspection :	10.01.2021	District:	Burari
Division :	Dumdum	Length (km):	0.315 Km
Name of the Road:	Bhojpur Road Hahar to Fagu Tola.		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <i>on going</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <i>yes</i>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <i>yes</i>
g)	Compaction of flank/slope & raincuts if any	Yes/No <i>No</i>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No <i>on going</i>
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	"
Unsatisfactory (U)	"

[Signature]
10.01.2021

J.E

A.E

(Signature)

NAME:

Dumdum

Dumdum