FIELD INSPECTION REPORT

Date of Inspection : -	13/01/25	District: later.
Division: Dencour.		Length (km): -0.945
Name of the Road: Ja	sipur mais	road to Nagroa Dera.
Scheme/Programme:	MAINTENANCE	
ackage No.:		Road Id No.:
Status of the Project:		ed/Under Maintenance
Work is a case of:	New Connectivity	Up gradation/ Maintenance

Work is a case of: New Connectivity/Op gradation Maintenance		nicentermania).
SI No	Parameters to be checked	Remarks
i e	Pavement	
a)	Road Junction condition	√s/U
b)	Condition of Surfacing	√S/U
c)	Riding Quality	vs/U
d)	Road Camber	vs/u
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
222:14	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	√S/SRI/U
c)	Condition of railings/slab/approach for Bridges	8/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4, 1	Complaince History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

Nignal 124

NAME: Nigmanand Mapto

DESIGNATION: - 5. Eg.