

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- unsar katra pwa Road to Jagarnathpur Hathani pwa Road.
(Bochaha)

(A) For Road: ✓

1. Damage Location/Chainage :- 0.100, 0.250, 0.500km, 0.90km, 1.50km, 2.20km, 3.50km
2. Damage Length :- 958.86 (0.95886km)
3. Nature of Damage :- (4.80km)
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.958 km (0.95886km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


15.12.20

Signature

(Name of Inspection)

EE

RWD Work Division,
muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Unserkatra PWD Road to Jagarnathpur Hathauri PWD Road

District Muzaffarpur

Block Bochaha


Division Muzaffarpur East-2


Length of Road (in Km) 4.800 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	17.203
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	17.203
TOTAL COST OF PROJECT IN LACS =		17.203


Say 17.20 lac


JE
RWD


AE
RWD


EE
RWD

Technically Approved for Rs 17.20 lac
(Rupees seventeen lac, twenty thousand only)


SE
RWD work circle
muzaffarpur