

Date of Inspection: 14/01/21 District: Nalanda
 Division: 11/55 Length (km): 1.77 km
 Name of the Road: Kadiya, a main road to Bhatia north in Dargah
 Scheme/Programme: MAINTENANCE Maintenance
 Village No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance Under Maintenance
 Work is a case of: New Connectivity/Up gradation/Maintenance Up gradation

I. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SR S
b)	Condition of Surfacing	SR S
c)	Riding Quality	SR S
d)	Road Camber	SR S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes No —
f)	Contraction Joints provided or not (CC Pavement)	Yes No —
g)	Compaction of flank/slope & raincuts if any	Yes No —
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U S
c)	Condition of railings/slab/approach for Bridges	S/SR/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes No Y
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

AE: Pradyumn Kumar Singh
 JE

(Signature)
 14/1/21
 21