

FIELD INSPECTION REPORT

Date of Inspection :	09-01-2024	District:	Naogaon
Division:	Qazigund	Length (km):	1.210 km
Name of the Road:	Sabot Path to Pashan Bhabha		
Scheme/Programme:	MAINTENANCE		
Package No.:	-	Road ID No.:	10502701213
Status of the Project:	Ongoing/Completed/Under Maintenance	09-01-2024	
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/N	
b)	Condition of Surfacing	S/N	
c)	Riding Quality	S/N	
d)	Road Camber	S/N	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of Rank/slope & rineaus if any	Yes/No	
2.	Gross Draining		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRU	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRU	
c)	Condition of railings/slab/approach for Bridges	S/SRU	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
N/A 09-01-2024			
4.	Geopettice Efficacy		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Chu
09-01-2024
(Signature)

NAME: SHALEEN SINHA
DESIGNATION: T. G.