

FIELD INSPECTION REPORT

Date of Inspection :	07-01-2021	District:	Nawada
Division :	Rasauli	Length (km):	2.06 km
Name of the Road: Nadaura Path to Netra			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.: 10502701215	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
SL No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & runcuts if any		Yes/No
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	S -
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

Om
(Signature)
07-01-2021

NAME: SHAILEN SINGH

DESIGNATION: D.E