


**FIELD INSPECTION REPORT**

Date of Inspection : 30/12/2020	District: L. Champaran	
Division: Bellahn	Length (km): 2.760 K.M	
Name of the Road: Tagdispur to Tagiraha		
Scheme/Programme: MAINTENANCE		
Package No.: NMGT (Gen)	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance	ONSOLAS	
Work is a case of:	New Connectivity/Up gradation/ Maintenance New con.	
Sl.No.	Parameters to be checked	Remarks
1.	<b>Bitumen</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note! Work in Progress

  
30/12/2020  
(Signature)

NAME: SUNIL KUMAR

DESIGNATION: J.T