

FIELD INSPECTION REPORT

Date of Inspection : 18.12.20	District: West Champaran
Division : Bettiah	Length (km): 0.910 km
Name of the Road: Panchayat Raj Hathi me - Gandak near he apar post, kofra	
Scheme/Programme: MAINTENANCE	NABARD
Package No.:	Road Id No.: 31808800304
Status of the Project: Ongoing/Completed/Under Maintenance	Completed.
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameter to be checked	Remarks
1.	Statement	
a)	Road Junction condition	S ✓ S/U
b)	Condition of Surfacing	S ✓ S/U
c)	Riding Quality	S ✓ S/U
d)	Road Camber	S ✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No S
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No S
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No S
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note: - work completed.

Signature: 18.12.20
(Signature)

NAME:

DESIGNATION:

J.E.

Scanned by CamScanner

Scanned by CamScanner