

FIELD INSPECTION REPORT

| | |
|---------------------------------|------------------------|
| Date of Inspection : 31/12/2020 | District: W. Champaran |
| Division: Bettiah | Length (km): 2.290 K.Y |

| | |
|--|--|
| Name of the Road: Ramnagar Bankat clone to Nambatoli | |
| Scheme/Programme: MAINTENANCE | |

| | |
|--|--------------|
| Package No.: MH54 (1c) | Road Id No.: |
| Status of the Project: Ongoing/Completed/Under Maintenance | ONGOING |

| | |
|--------------------|---|
| Work is a case of: | New Connectivity/Up gradation/ Maintenance New Connectivity |
|--------------------|---|

| Sl No. | Parameters to be checked | Remarks | |
|--------|--|---------|--|
| | | | |
| 1. | Pavement | | |
| a) | Road Junction condition | S/U | |
| b) | Condition of Surfacing | S/U | |
| c) | Riding Quality | S/U | |
| d) | Road Camber | S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No | |
| g) | Compaction of flank/slope & raincuts if any | Yes/No | |
| | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U | |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No | |
| 4. | Compliance History | | |
| a) | Status of ATR's & any others | | |

Overall Rating :

| | |
|---|-----|
| Satisfactory (S) | N/A |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

Note:- Work in Progress


31/12/2020
(Signature)

NAME: SUNIL CHHAP

DESIGNATION: J.E