

## FIELD INSPECTION REPORT

Date of Inspection :	08.01.2021	District:	Nawada
Division :	Rajauli	Length (km):	0.50 Km
Name of the Road:	Nadaura Path to Netra		
Scheme/Programme:	MAINTENANCE X		
Package No.:	BR-25R-467	Road Id No.:	10502702139
Status of the Project:	Ongoing/Completed/Under Maintenance N/A		
Work is a case of:	New Connectivity/Urgent/graduation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raintcuts if any	Yes/No
2.	Cross Drainage	NA
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)  
Arbind Kumar Singh  
12/1/2021

NAME:

Arbind Kumar Singh

DESIGNATION: A.E. Roh