

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Dighlaker

2 Name of Block/Road :- Harthaus PWD Rd to Katen choudhary bridge.
constr. of bridge 6X19.36M. (Bachan)

(A) For Road: ☒

1. Damage Location/Chainage :-

2. Damage Length :- 61.0m. (.

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:- Brick bats.

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:

(iv) Restored Length :-

(B) For Bridge: ☒

1. Damage Location/Chainage :- 0 to 0.061 km.

2. Damage Length :- 0.061 km

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:- Brick bats.

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :- 0.061 km

Signature of JE/AE/EE

Signature

(Name of Inspection)

EE
PWD work Division
muzaffarpur East-1

GENERAL ABSTRACT

Name of Road ^{Bridge At} H.L. Hathauri PWD Rd to Kafen Chaudhary

District Muzaffarpur

Block Bochaha

Division Muzaffarpur East-2

Length of Road (in Km) 4.200 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	7.260
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	7.260
TOTAL COST OF PROJECT IN LACS =		7.260

Says. 7.26 Lac

Santosh Kumar
20/11/2020

AB
20/11/20

JE

RWD

AN
20/11/20

AE

RWD

San
20/11/20

EE

RWD

Technically Approved for Rs. 7.26 Lac.
(Rupees seven Lac, twenty six thousand only.)

SE
4-11-21
PWD works circle
muzaffarpur.