

GENERAL ABSTRACT

Name of Road Munni to Munni Village

District Muzaffarpur

Block Gaighat


Division Muzaffarpur East-2


Length of Road (in Km)

1.500 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
1	Jhama metal	14.953
2	Sand Filling	0.162
3	Sand Bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	14.953 15.115
TOTAL COST OF PROJECT IN LACS =		14.953 15.115


SAY. 14.95 Lac.


JE
RWD


AE
RWD


EE
RWD

Technically Approved for Rs 14.95 Lac.
(Rupees fourteen Lac, ninety five thousand only.)


SE
RWD work circle
muzaffarpur

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan Dabhtakar
2. Name of Block/Road - murni to murni village (haigted)

A. For Road ✓

1. Damage Location/Chainage : 0.40 km, 0.45 km, 0.70 km, 0.85 km, 1.20 km
2. Damage Length : 0.1605 km
3. Nature of Damage :
4. Details of Restoration Works : (Length = 1.50 km)
i. Material being used in Restoration works : brick bats
ii. Equipments/Tools being used in Restoration works:
iii. Procedure taken up in Restoration works :
iv. Restored Length : 0.1605 km

B. For Bridge ✗

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
i. Material being used in Restoration works :
ii. Equipments/Tools being used in Restoration works:
iii. Procedure taken up in Restoration works :
iv. Restored Length :

Signature of JE/AE/EE


Signature

(Name of Inspector)

EE

RWD WORK DIVISION
Muzaffarpur East-1