

GENERAL ABSTRACT

Name of Road Ext. of NH-77 Road to Sahila Rampur

District Muzaffarpur

Block Bochaha


Division Muzaffarpur East-2


Length of Road (in Km) 11.240 Km

| Sl. No. | DESCRIPTION | AMOUNT (LAKHS) |
|---------------------------------|-----------------|----------------|
| 1 | Jhama metal | 20.183 |
| 2 | Sand Filling | 0.000 |
| 3 | Sand bag | 0.000 |
| 4 | Bamboo Piles | 0.000 |
| | GRAND SUB TOTAL | 20.183 |
| TOTAL COST OF PROJECT IN LACS = | | 20.183 |


SAY = 20.18 Lac


JE
RWD


AE
RWD


EE
RWD

Technically Approved for Rs 20.18 lac
(Rupees twenty lac. eighteen thousand only).


SE
RWD work circle
muzaffarpur

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gayam vibhakar

2 Name of Block/Road :- Ext. of NH 77 Road to Sahila Rampur (Bodaha)

(A) For Road: ✓

1. Damage Location/Chainage :- 0.300 km, 0.550 km, 0.850 km, 1.20 km, 1.50 km,
2. Damage Length :- 1.232 km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats. (Length = 11.24 km)
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 1.232 km

(B) For Bridge: X

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


16.12.20

Signature

(Name of Inspection)

EE

RWD WORK DIVISION
MUZAFFARPUR (C&T-1)