

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Bhabhaker

2 Name of Block/Road :- manghauri panchayat under Raghobatti village panchayat
to Nadi lake (Bachan)

(A) For Road: ✓

1. Damage Location/Chainage :- 0.010 km, 0.090 km, 0.250 km, 0.450 km, 0.650 km, 0.900 km
2. Damage Length :- 379.0 m (0.379 km)
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.379 km

(Length = 1.242 km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE

RWD work Division

Muzaffarpur East-I

GENERAL ABSTRACT

Name of Road Manjhauli Panchayat Under Raghupati Village Paswan Tola to Nadi Tak
District Muzaffarpur
Block Bochaha
Division Muzaffarpur East-2
Length of Road (in Km) 1.242 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	7.262
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	7.262
TOTAL COST OF PROJECT IN LACS =		7.262

SAM. 7.26 Lac.

Satish v. Panwar
20/12/2020

JE
RWD

AE
RWD

RWD

Technically Approved for Rs 7.26 Lac.
(Rupees seven LAC, twenty six thousand only.)

SE
RWD work circle
muzaffarpur