

FIELD INSPECTION REPORT

Date of Inspection :	31/12/2020	District:	Lakhisarai
Division :	Lakhisarai	Length (km):	2.812 K.m.
Name of the Road:	Pakahi Muchari - Sethua MaX		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-19R-062	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance✓		
Work is a case of:	✓New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A. S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N.A. S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Sd/-
31/12/2020
AF

(Signature)

NAME:

REGISTRATION