

FIELD INSPECTION REPORT

Date of Inspection :	31/12/2020	District:	Lakhisarai
Division :	Lakhisarai	Length (km):	1.113 k.m.
Name of the Road:	To 3 Shivrona village to Halai		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-19R-061	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	✓ New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No	
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	N.A. S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	N.A.	

Overall Rating :

Satisfactory (S)	15
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

S. K.
31/12/2020
A.E.

(Signature)

NAME:

DESIGNATION: