FIELD INSPECTION REPORT

Date of Inspection: 09.01.2021 Distrcit: SARAN

Division: SONPUR Length (km):0.800

Name of the Road: Parsa Gandak Yojana Se Shiv Kumar Singh Ke Ghar Hote Huye To Prem

Sagar Ke Ghar Tak

Scheme/Programme: MMGSY Gen.

Package No: Road ID No:

Status of The Project: MAINTENANCE

Work is a case of: Maintenance

Sl.No	Parameters to be checked	Remarks
1	Pavement	THE COTON
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality •	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
f)	Contraction Joints provided or not (CC Pavement)	5 , ,
g)	Compaction of Flank/slope & raincuts if any	SRI
2	Cross Drainage	
a)	Condition of head walls in Hume pipe Culverts including its painting	s distrib
b)	Condition of Abutment & Wing Walls, Slab in RCC Culverts	S
c)	Condition of railings/slab/approach for Bridges	S
3	Raod Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	Compliance History	
a)	Status of ATR's any others	NO

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Signature Signature

NAME:- RAJEEV RANJAN KUMAR DESIGNATION: JUNIOR ENGINEER