

FIELD INSPECTION REPORT

Date of Inspection : 18/01/21		District : East Champaran
Division : Chakia		Length (Km): 1.604 km
Name of the Road : Bhimeswar Chhapra Main Chhapra PMWSY to Madhepuri Gomud Road		
Scheme/Programme : MMWSY		Road ID No.:
Package No.:		
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	U
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	No
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	U

Note:- BT ^{surface} expose in some change and Road furniture painting required


 (Signature) 18/1/21

NAME :

DESIGNATION :