

FIELD INSPECTION REPORT

Date of Inspection : 07/1/2021	District: East Champaran
Division : WORKS Divn DHAKA	Length (km): 2.139
Name of the Road: Jagiraha Kachahriya Road to Semra Pul Bari	Via Barai to Athmuhon W-II
Scheme/Programme: MAINTENANCE	Mukhya Mantri Gram Sadak Yojana
Package No.:	Road Id No.: 31708613005
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U ✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	U

Note - Five year Maintenance not done by Contractor.

07/01/2021
(Signature)

NAME: SANJAY KUMAR

DESIGNATION: J.E