FIELD INSPECTION REPORT

Date	of Inspection : /	5-01-2021	District: East Champaran		
10-10-12-12	ion: 31 Khorna		Length (km): 2.532 km		
		ngari Nimuis	per Road to Nimuiga Nahor	- Yadav To	
30-3 PCS123-549-54		MAINTENANCE	I D171V		
Package No.: Status of the Project: Ongoing/Complete		Ongoing/Complete	Road Id No.: 31708613514		
			w Connectivity/Up gradation/ Maintenance		
Sl. No.		Parameters to be checked		Remarks	
1.	Payement				
a) Road Junction con		condition	Company of the Art and the State Company of the Sta	<i>S/</i> Ú	
b)	Condition of Surfacing			∽ S /U	
c)	Riding Quality			−8/U	
d)	Road Camber			_S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainag	6			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b) ·	Condition of Abutment & Wing walls, Slab in RCC culverts.			-S/SRI/U	
;)	Condition of railings/slab/approach for Bridges			S/SRI/U	
	Road Furnitur				
	Whether sign stones/Pavemen	boards/informatory t road markings are	//cautionary Board/km & 200n e provided and maintained	Yes/No	
	Compliance Hi	itory			
	Status of ATR's	& any others		NO ATK	

Overall Rating

Satisfactory (S)	151
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

905-1. 15/01/2021 (Signature)

NAME: Nand Gobol.

At, R-WD, Dhaka.