

FIELD INSPECTION REPORT

Date of Inspection : 18.1.21	District: Aurangabad
Division : Aurangabad	Length (km): 0.8575
Name of the Road: Tos to Dehga	
Scheme/Programme: MAINTENANCE	
Package No.: BR-D2R-612	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Home pipe culverts including its painting	S SRU
b)	Condition of Abutment & Wing walls, Slab in RCC culver	S SRU
c)	Condition of railings/slab/approach for Bridges	S SRU
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRU)

Unsatisfactory (U)

U

18.1.21
(Signature)
AE, Kurnool

NAME: