

FIELD INSPECTION REPORT

Date of Inspection : 17.01.21	District: West Champaran	
Division : Bettiah	Length (km): 0.700 km	
Name of the Road: L 026 PMGSY road to Fatehpur Badajitola.		
Scheme/Programme: MAINTENANCE	GT SNY	
Package No.:	Road Id No.: 31808818015	
Status of the Project: Ongoing/Completed/Under Maintenance	Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1. Statement		
a)	Road Junction condition	S/SU
b)	Condition of Surfacing	S/SU
c)	Riding Quality	S/SU
d)	Road Camber	S/SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S Yes/No
f)	Contraction Joints provided or not (CC Pavement)	S Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No SRI
4. Compliance History		
a)	Status of ATR's & any others	YES

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Signature: 17.01.21
(Signature)

J.E.

NAME:

DESIGNATION:

Scanned by CamScanner

Scanned by CamScanner