FIELD INSPECTION REPORT

	of Inspection : /	3/01/2021	District: East chambara	n
	ion: Sikhurn		Length (km): 9.1964	
Name	of the Road:	vrosahia Vijay	ee pain to Vijagel forerea	Report
Scheme/Programme: MAINTENANCE Package No.:			MMGS	0/
	of the Project:	Ongoing/Complete	Road Id No.: 3170860	1332
	is a case of:		Up gradation/ Maintenance	
SI. No.	ESTAL SALES AND ADDRESS OF THE PARTY OF THE	Parameters to	HT 100 P P T 100	
1.	Pavement		o De Checked	Remarks
-	the second second		All and the second	and the same
a)	Road Junction			S/U
b)	Condition of S	urfacing		S/U
c)	Riding Quality			S/U
d)	Road Camber			\S/U
e) ·	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drainag	•		
a)	Condition of he	S/SRI/U		
Condition of Abutment & Wing wall				S/SRI/U
)	Condition of rai	lings/slab/approach	for Bridges	S/SRI/U
	Road Furnitur			
S	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
C	ompliance His	tory	AND THE RESIDENCE OF THE PARTY	-
S	tatus of ATR's	& any others		INDATR

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)/01/2021

NAME: Namel Gobel.

At. R.W.D. Dheka.