## FIELD INSPECTION REPORT

			_	
Date of 1	Inspection: 16/1/2021	Istrict: Malanda.		
Division: Biharelaris Length (km):				
Name of	The Road: Sore-Noawern R	bad in chalclin mos	e to Jet	
Scheme	Programme: MAINTENANCE	MMGSY (SC)		
Packago	c No.:	Road Id No.:		
	of the Project: Ongoing/Completed/U			
Work is		gradation/ Maintenance	41.000	
Sl. No.	Parameters to be	Remarks		
1.	Pavement			
a)	Road Junction condition		S/U	
b)	Condition of Surfacing		S/U	
c)	Riding Quality		S/U	
d)	Road Camber	S/U		
e)	Whether free from defects such aggregates in case of CC Pavement.	Yes/No		
f)	Contraction Joints provided or not (CC	Yes/No		
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		s/sri/u	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		s/sri/u	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No	
4,	Compliance History	And the think		
a)	Status of ATR's & any others		140	
)verall R	Rating			
· · ··································	Satisfactory (S)		C	

Satisfactory (S)	C
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Mukes Yaday
DESIGNATION: PE