

FIELD INSPECTION REPORT

Date of Inspection: 12/01/2021	District: Sheikhpura	
Division: Sheikhpura	Length (km): 1.050 km	
Name of the Road: Basigha Sheikhpur Saray to Bishanpur		
Scheme/Programme: MAINTENANCE	M/M/GS4 (Under sys. Maint)	
Package No.:	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained.	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Note:-
At some places damaged by NAL-JAL Yagna

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

SV
12/01/2021
(Signature)

NAME: SANGRAM HEMBROM
DESIGNATION: A.E.