

FIELD INSPECTION REPORT

Date of Inspection : 18/01/21		District : East Champaran
Division : Chakia		Length (Km): 0.650 km
Name of the Road : L033 se paowan-tola		
Scheme/Programme :		CITSNY
Package No.:		Road ID No.:
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes
g)	Compaction of flank/slope & raincuts if any	Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	NO
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	SRI
	Unsatisfactory (U)	

Road furniture fastening Required.


 (Signature)

NAME :

DESIGNATION :