


FIELD INSPECTION REPORT

Date of Inspection : 17-01-2021		Sheikhpura	
Division : Sheikhpura		Length (km): 0.400 km	
Name of the Road: Soikandara-Sheikhpura Path to Basant Anurakhi Tola			
Scheme/Programme: MAINTENANCE		Ongoing Road	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
		Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of Bank slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature) 17.01.2021

NAME: PANKAJ KUMAR
 DESIGNATION: JE, Chawara