Garkha

FIELD INSPECTION REPORT

Date o	f Inspection :	17/1/2021	District: chapsa.		
			Length (km): 1.410 len	th (km): 1.410 lem.	
Name of the Road: NH-102 to yadawfola					
	Scheme/Programme: MAINTENANCE MM 454 (HDB)				
Package No.:		Road Id No.:			
Status of the Project: Work is a case of:		Qngoing/Completed/Under Maintenance New Gonnectivity/Up gradation/ Maintenance			
Constitution of the publication of the state of the		Parameters to be checked		, it 79 x7 miles [64.7]	
SI. No.	一一位。这样是	人。 [10] A. · · · · · · · · · · · · · · · · · ·	MAN WAR A CALL TO ST. 1-4-	Remarks	
1.	Pavement				
a)	Road Junction condition			~S/U	
b)	Condition of Surfacing			-S/U	
c)	Riding Quality			S/U	
d)	Road Camber .			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of	Yes/No .			
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
p) .	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture			Table 14 and 1	
a) s	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No				
4. (ompliance His	tory		rente issues e La manualità di sot	
a) S	tatus of ATR's	& any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SR1
Unsatisfactory (U)	

NAME:

DESIGNATION:

(Signature)