

FIELD INSPECTION REPORT

Date of Inspection :	12-01-2021	District:	GAYA
Division :	SHERGHATI	Length (km):	0.712
Name of the Road:	L023 TO SHAHPUR		
Scheme/Programme:	MAINTENANCE	MMGSF	
Package No.:		Road Id No.:	
Status of the Project:	☒ Ongoing/Completed/Under Maintenance		
Work is a case of:	☒ New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U N-A.	
b)	Condition of Surfacing	S/U Gr-III	
c)	Riding Quality	S/U N-A.	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NOT done	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No " "	
g)	Compaction of flank/slope & raincuts if any	Yes/No N-A.	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N-A.	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	1
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	1

The Road in question is in 'On-going' stage. WBM- Gr-III has been done. RCC is not yet constructed.

(Signature) : [Signature]
12.01.21

NAME: Booj Kishore Prasad
DESIGNATION: Assistant Engr/Dobhi