

FIELD INSPECTION REPORT

Date of Inspection : 12-01-2021	District: GAYA	
Division : SHERGHATI	Length (km): 1.869	
Name of the Road: T03 to Kohadwa Tola old Byefan kesape		
Scheme/Programme: MAINTENANCE	MMGSF	
Package No.:	Road Id No.:	
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance		
Work is a case of: ☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U N-A.
a)	Road Junction condition	S/U Gr-III
b)	Condition of Surfacing	S/U N-A.
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NIL

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

The Road in question is in "On-going" stage. WBM-G-III has been completed. PMCF is yet to be done.

NAME:

Rosy Krishna Borsani

DESIGNATION:

Assistant Engr/Dobhi

(Signature)

12-01-21