FIELD INSPECTION REPORT

Date of Inspection : 56/1 /202/ District: W.		District: W. Chansparar)	
Division: C 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
Name of the Road: Avery Road Ke Bishunder Sink be gear to Hardigy -				
Scheme/Programme: MAINTENANCE - Hishandor Sight Jolg				
Package No.: MMGSY (IT) Road Id No.:				
Status of the Project: Ongoing/Completed/Under Maintenance ONGOING				
Work is a case of: New Connectivity/Up gradation/ Maintenance № №				
Shillo.	Parameters to he disclared		Ramarks	
4	Parament			
a)	Road Junction condition		S/U	
b)	Condition of Surfacing		S/U	
c)	Riding Quality		S/U	
d)	Road Camber .		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
4	Cross Brainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No	
4	Compliance History			
a)	Status of ATR's & any others			

Overall Rating

j'	
Satisfactory (S)	H/A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note: work in Progrev

(Signature) Tool

NAME: SUNIL QUHAP

designation: \mathcal{J}

Scanned by CamScanner