FIELD INSPECTION REPORT

,					
Date of Inspection :			Dhiriet: W. Chansparan		
Division: Bettzah			Length (km): 0.490 B.H		
Name of	the Road: Haz	ari Cample	to Bonggli folg		
		INTENANCE	15		
Package No.: MMGSY (ST)			Road Id No.:	G	
Status of the Project: Ongoing/Completed/Under Maintenance ONGC Work is a case of: New Connectivity/Up gradation/ Maintenance N					
SHOW .	Parameters to Dockerd			Remarks	
<u>a</u>	Pinament				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber .			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any Yes/				
	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4	Compliance History				
a)	Status of ATR's &	any others			
				- the same of the	

Overall Rating

	_
Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note! - Work in Propress

(Signature) 01/2021

NAME; SUNIC RUHAP

designation: $f \in$

Scanned by CamScanne